

Test Report



Report No. A221002539210100202R1

Page 1 of 5

Company Name
Shown on Report GradConn Ltd

Address 209 Minsheng Road, Longtan District, Taoyuan City, Taiwan 32554

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client

Sample Name Isolated RP SMA Straight Bulkhead Jack with O-ring Rated to IP67/68
Lot No. RFCT-SMA086-F78
Sample Receiving State Normal
Sample Received Date Jan. 20, 2021
Testing Period Jan. 20, 2021-Jan. 29, 2021

Test Requested

| No. | Test Item |
|-----|-----------|
| 1 | IP6X |

Test Result(s): Please see the following pages.

Approved by Roger Xiao

Date Feb. 24, 2021

Roger xiao
Approved Signatory

No. R94B5E0611

Centre Testing International Group Co., Ltd.

Hongwei Industrial Zone, Bao'an 70 District, Shenzhen, Guangdong, China



Test Report


Report No. A221002539210100202R1

Page 2 of 5

Tested Sample(s)

| Sample No. | Sample Name | Quantity |
|-------------------|--|----------|
| A2210025392101002 | Isolated RP SMA Straight Bulkhead Jack with O-ring Rated to IP67/68 | 1pc |

Sample Photo(s)



A2210025392101002

Test Report

Report No. A221002539210100202R1

Page 3 of 5

Test Item: IP6X

1. Test Equipment

| Equipment Name | Model |
|----------------|---------|
| Test probe | Φ1.0mm |
| Dust Tester | KXT1410 |

2. Environmental Conditions

Temperature: 25.6 °C; Humidity: 62 %RH

3. Test Standard: IEC 60529:2013

4. Test Condition

Use a test probe with a diameter of 1mm to probe the gap part of the sample with a force of 1N.

Put the sample in a negative pressure state, the pumping speed is 40-60 times the volume of the shell per hour, and the pressure difference between the pressure in the shell and the atmospheric pressure is less than 2kPa, and continue the test. Place it in a dust-proof test box for 2h.

5. Test Result(s)

| Sample No. | Criterion | Test result(Visual inspection) | Conclusion |
|--|---|---|------------|
| A2210025392101002 | The probe cannot enter, and there is no dust inside the sample. | The probe cannot enter, and there is no dust inside the sample. | Pass |
| Note: The judgment basis is provided by the customer | | | |

股
VAL GROUP
用章
Service

Test Report

Report No. A221002539210100202R1

Page 4 of 5

Test Photo(s)




A2210025392101002



A2210025392101002

Sample Photo(s) after the test



A2210025392101002

Remark: The testing data and result(s) in this report is(are) just for scientific research, education, internal quality control and product development etc.

Note: This testing report revised "Sample Name, Test Photo(s), Sample Photo(s) after the test" based on the original report of No. A221002539210100202. This testing report displaces the original one which was invalid since the date of this testing report released.

华测检测
CENTRE TESTING INTERNATIONAL

Test Report

Report No. A221002539210100202R1

Page 5 of 5

Statement:

- 1.This report is considered invalid without approved signature, special seal and the seal on the perforation;
- 2.Company Name and Address shown on Report, the sample(s) and sample Information was/were provided by the applicant who should be responsible for the authenticity which CTI hasn't verified;
- 3.The result(s) shown in this report refer(s) only to the sample(s) tested;
- 4.Without written approval of CTI, this report can't be reproduced except in full;
- 5.In case of any discrepancy between the English version and Chinese version of the testing reports(if generated), the Chinese version shall prevail.

*** End of Report ***

