CTI华测检测

Test Report



Report No. A223054740410102

Page 1 of 5

Company Name	GRADCONN LTD
Shown on Report	ORADCONN LID
Address	209 MINSHENG ROAD, LONGTAN DISTRICT, TAOYUAN CITY,
	TAIWAN 32554

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client

Sample Name	Ipex MHF I to 1.13 cable to RP SMA S/T Bulkhead Jack w/o- ring	Ipex MHF I to 1.13 cable to SMAS/T Bulkhead Jack w/o-ring
Part No.	CAB603RF-XXXX-XX-X-1	CAB602RF-XXXX-XX-X-1
Sample Receiving State	Normal	Normal
Sample Received Date	Oct. 23, 2023	
Testing Period	Oct. 23, 2023-Oct. 30, 2023	

Test Requested

No.	Test Item	
1	IPX6	

Test Result(s): Please see the following pages.

Approved by Rager Trao	Date	Oct. 30, 2023
Roger xiao Approved Signatory FERMATOW Centre Desting International Group Co., Ltd. 检验检测专用章 Inspection & Testing Services	Hongwei Industrial Zone, Bao'an 7	No. R2869673CB 10 District, Shenzhen, Guangdong, China




Report No. A223054740410102

Page 2 of 5

Tested Sample(s)

Sample No.	Sample Name	Туре	Quantity
A2230547404101001	Ipex MHF I to 1.13 cable to RP SMA S/T Bulkhead Jack w/o-ring	CAB603RF-XXXX- XX-X-1	1pc
A2230547404101002	Ipex MHF I to 1.13 cable to SMAS/T Bulkhead Jack w/o-ring	CAB602RF-XXXX- XX-X-1	1pc

Sample Photo(s)



A2230547404101001

A2230547404101002





Report No. A223054740410102

Test Item: IPX6

1. Test Equipment

Equipment Name	Model
Waterproof grade testing machine	JX1040

2. Environmental Conditions

Temperature:26.2°C; Humidity:54% RH

3. Test Standard: IEC 60529:2013

4. Test Condition

Water flow:100L/min

Nozzle distance sample 2.5-3m

Nozzle inner diameter:12.5mm

Turntable speed:1r/min

Test time:3min

5. Test Result(s)

Sample No.	Criterion	Test result (Visual inspection)	Conclusion
A2230547404101001	There is no water inside the sample, if there is water can not enter or endanger live parts.	No water enters the sample	Pass
A2230547404101002	There is no water inside the sample, if there is water can not enter or endanger live parts.	No water enters the sample	Pass

Reversion The Service

Page 3 of 5



Report No. A223054740410102

Test Photo(s)



A2230547404101001

A2230547404101002

Sample Photo(s) after the test 43 44 45 46 47 48 49 51 52 53 54 55 56 57 58 59 61 62 63 64 65 66 67 68 69 71 4 15 16 17 18 19 21 22 23 24 25 26 27 28 29 31 32 33 34 35 36 37 38 39 СТІ 60 70 50 9 20 сті 30 40 A2230547404101001 A2230547404101001 51 52 53 54 55 56 57 58 59 61 62 63 64 65 66 67 68 69 71 4 15 16 17 18 19 21 22 23 24 25 26 27 28 29 31 32 33 34 35 36 37 38 39 43 44 45 46 47 48 49 сті 60 70 50 20 сті 30 40 A2230547404101002 A2230547404101002

Page 4 of 5



Report No. A223054740410102

Remark: The testing data and result(s) in this report is(are) just for scientific research, education, internal quality control and product development etc.

Statement:

- 1. This report is considered invalid without approved signature, special seal and the seal on the perforation;
- 2. Company Name and Address shown on Report, the sample(s) and sample Information was/were provided by the applicant who should be responsible for the authenticity which CTI hasn't verified;
- 3. The result(s) shown in this report refer(s) only to the sample(s) tested;
- 4. Without written approval of CTI, this report can't be reproduced except in full;
- 5.In case of any discrepancy between the English version and Chinese version of the testing reports (if generated), the Chinese version shall prevail.

*** End of Report ***

Page 5 of 5